



Figure 1: Lake Road Lake Road looking southwest at graded watershed runoff channel showing displaced wattle and manure piles; flow had backed up at culvert.



Figure 2: Lake Road looking south at eroding graded slope.



Figure 3: Tributary of Peaslee Creek from graded area at Lake Road



Figure 4: Turlock Lake State Recreation Area campground at river mile 42 below Peaslee Creek